

Problematic Mineral and Landfill Sites

Test Valley

Site Code	Site Name	Area	Issues
TTV008	Broadlands Lake, South	12.3 ha	<ul style="list-style-type: none"> • Cumulative impacts, including <ul style="list-style-type: none"> ➤ Visual/landscape impact on river valley landscape ➤ Ecological/biodiversity ➤ Flooding, Access ➤ Airport safety
TTV009	Lee Lane, Nursling	31.57ha	<ul style="list-style-type: none"> • Contrary to policy – landfill is only acceptable as means of restoring mineral workings
TTV015	Cutty Brow, Andover (b)	46.9 ha	<ul style="list-style-type: none"> • Site is already worked and restored
TTV016	Cutty Brow, Andover (c)	30.3 ha	<ul style="list-style-type: none"> • Site is already worked and restored
TTV019	The Triangle, Ridge	71.54 ha	<ul style="list-style-type: none"> • Site is subject to significant hydrogeological issues, precautionary principle indicates it should be rejected • Inspector's Report dismissed the Appeal to extract sand & gravel in 07/04/2003

Problematic Waste Sites

Test Valley

Site Code	Site Name	Area	Issues
TTV012	Long Term Car Park, Shepherds Spring Lane, Andover.	0.56 ha	<ul style="list-style-type: none">• The site is too small for a significant facility.